

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Sn:988579800333

Time:2024-10-17 14:47:45

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

## Vehicle Information

Make:PEUGEOT

VIN:VF3YBZMFB12M72808

Odometer:118309 miles

Vehicle Software Version:V10.38

## Inspection Result

The following systems are OK:

- 1.Engine ECU
- 2.Anti-lock Braking System (ABS) Or Electric Stability Program (ESP)
- 3.Built-in Systems Interface(Bsi)
- 4.Power Steering
- 5.Instrument Panel
- 6.Air Bag
- 7.Tachograph