



Make	MERCEDES-BENZ
Model	GLC 220d 4MATIC
Vin	WDC2539052F572852
Engine Specifications	Diesel <input type="checkbox"/>
Vehicle Type	SUV
Service Plan	N/A

Year	2019
Km	56125
Transmission	Automatic <input type="checkbox"/>
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

Radio / Entertainment	Good Condition <input type="checkbox"/>	Aircon Controls	Good Condition <input type="checkbox"/>
Cluster	Good Condition <input type="checkbox"/>	Electric Windows	Good Condition <input type="checkbox"/>

Exterior

Windscreen	Good Condition <input type="checkbox"/>	Mag Wheels	Not Applicable <input type="checkbox"/>
Side Mirrors / Electric	Good Condition <input type="checkbox"/>	Wiper Blades	Good Condition <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	56129 Km	Dip Stick	No Visible Leaks <input type="checkbox"/>
Oil Filter	No Visible Leaks <input type="checkbox"/>	Oil Filler Cap	No Visible Leaks <input type="checkbox"/>
Fuel/Diesel Filter	No Visible Leaks <input type="checkbox"/>	Fan Belt	Not Applicable <input type="checkbox"/>
Air Filter	Good Condition <input type="checkbox"/>	Fan belt Tensioner	Not Applicable <input type="checkbox"/>
Cabin Filter	Good Condition <input type="checkbox"/>	Alternator Belt	Not Applicable <input type="checkbox"/>
Spark Plugs	Good Condition <input type="checkbox"/>	Power Steering Belt	Not Applicable <input type="checkbox"/>
Brake Fluid	No Visible Leaks <input type="checkbox"/>	Aircon Belt	Not Applicable <input type="checkbox"/>
Antifreeze	No Visible Leaks <input type="checkbox"/>	Multi V belt	No Cracks <input type="checkbox"/>
Rear Main Seal	No Visible Leaks <input type="checkbox"/>	Engine Mountings	Good Condition <input type="checkbox"/>
Sump/Gasket	No Visible Leaks <input type="checkbox"/>	PCV Valve	Good Condition <input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Good Condition	<input type="checkbox"/>
Front Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Brake Pads	100%	<input type="checkbox"/>
Rear Brake Discs	Good Condition	<input type="checkbox"/>
Rear Brake Sensor	Good Condition	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	-Select-	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	No Visible Leaks	<input type="checkbox"/>
Brake Hose	No Visible Leaks	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	No Visible Leaks	<input type="checkbox"/>
Aircon Pump	No Visible Leaks	<input type="checkbox"/>
Aircon Condensor	No Visible Leaks	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	No Visible Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	No Visible Leaks	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	No Visible Leaks	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	No Visible Leaks	<input type="checkbox"/>

Ignition System		
Ignition Coils	Good Condition	<input type="checkbox"/>
Glow Plugs	Good Condition	<input type="checkbox"/>
Distrubutor	Good Condition	<input type="checkbox"/>
HT Leads	Good Condition	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="button" value="v"/>
Power Steering Pump	No Visible Leaks	<input type="button" value="v"/>
Wheel Alignment	Good Condition	<input type="button" value="v"/>
CV Joints	Good Condition	<input type="button" value="v"/>
CV Boots	No Visible Leaks	<input type="button" value="v"/>
Shocks Front	No Visible Leaks	<input type="button" value="v"/>
Shock Mountings Front	Good Condition	<input type="button" value="v"/>
Shocks Rear	Good Condition	<input type="button" value="v"/>
Stabilizer Links	Good Condition	<input type="button" value="v"/>
Wheel Bearings	Good Condition	<input type="button" value="v"/>
Bearing Hubs	Good Condition	<input type="button" value="v"/>
Control Arms	Good Condition	<input type="button" value="v"/>
Sideshafts/Seal	No Visible Leaks	<input type="button" value="v"/>
Propshaft	No Visible Leaks	<input type="button" value="v"/>
Wheel Nuts/Studs	Good Condition	<input type="button" value="v"/>
Tyres & Spare	Not Applicable	<input type="button" value="v"/>
Mag Wheels/Hub Caps	Good Condition	<input type="button" value="v"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="button" value="v"/>
Clutch Master	Not Applicable	<input type="button" value="v"/>
Clutch Slave	Not Applicable	<input type="button" value="v"/>
Clutch Cable	Not Applicable	<input type="button" value="v"/>
Gearbox	Good Condition	<input type="button" value="v"/>
Gear & Diff oil	No Visible Leaks	<input type="button" value="v"/>
Auto Transmission	No Visible Leaks	<input type="button" value="v"/>
Gear Selector	Good Condition	<input type="button" value="v"/>
Gear Linkages	Good Condition	<input type="button" value="v"/>

Ignition System		
Diagnostics	Good Condition	<input type="button" value="v"/>
Cyl Leakage Test	No Visible Leaks	<input type="button" value="v"/>
Road Test	Good Condition	<input type="button" value="v"/>
Handling	Good Condition	<input type="button" value="v"/>

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

JOHN TSIPA

Date of Inspection

21-Nov-2024