



Make	HYUNDAI	
Model	VENUE 1.0 TGDI FLUID DCT	
Vin	MALFB81AVPM372933	
Engine Specifications	1.0	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2023	
Km	47929	
Transmission	Automatic	<input type="checkbox"/>
Colour	WHITE	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	No Fault Code	<input type="checkbox"/>	Aircon Controls	No Fault Code	<input type="checkbox"/>
Cluster	No Fault Code	<input type="checkbox"/>	Electric Windows	No Fault Code	<input type="checkbox"/>

Exterior

Windscreen	Within Specification	<input type="checkbox"/>	Mag Wheels	Within Specification	<input type="checkbox"/>
Side Mirrors / Electric	No Fault Code	<input type="checkbox"/>	Wiper Blades	Good Condition	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service		Km	Dip Stick	Within Specification	<input type="checkbox"/>
Oil Filter	No Visible Leaks	<input type="checkbox"/>	Oil Filler Cap	Within Specification	<input type="checkbox"/>
Fuel/Diesel Filter	Not Applicable	<input type="checkbox"/>	Fan Belt	Not Applicable	<input type="checkbox"/>
Air Filter	Within Specification	<input type="checkbox"/>	Fan belt Tensioner	Within Specification	<input type="checkbox"/>
Cabin Filter	Within Specification	<input type="checkbox"/>	Alternator Belt	No Cracks	<input type="checkbox"/>
Spark Plugs	No Fault Code	<input type="checkbox"/>	Power Steering Belt	Not Applicable	<input type="checkbox"/>
Brake Fluid	No Visible Leaks	<input type="checkbox"/>	Aircon Belt	No Cracks	<input type="checkbox"/>
Antifreeze	No Visible Leaks	<input type="checkbox"/>	Multi V belt	No Cracks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Within Specification	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Within Specification	<input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="button" value="v"/>
Front Brake Discs	Within Specification	<input type="button" value="v"/>
Front Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Brake Pads	-Select-	<input type="button" value="v"/>
Rear Brake Discs	Not Applicable	<input type="button" value="v"/>
Rear Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Drums	Within Specification	<input type="button" value="v"/>
Rear Linings	80%	<input type="button" value="v"/>
Brake Master	No Visible Leaks	<input type="button" value="v"/>
Hand Brake	Within Specification	<input type="button" value="v"/>
Brake Calipers	No Visible Leaks	<input type="button" value="v"/>
Brake Hose	No Visible Leaks	<input type="button" value="v"/>

Cooling System		
Radiator	No Visible Leaks	<input type="button" value="v"/>
Radiator Hoses	No Visible Leaks	<input type="button" value="v"/>
Waterpump	No Visible Leaks	<input type="button" value="v"/>
Thermostat	No Visible Leaks	<input type="button" value="v"/>
Aircon Gas	No Visible Leaks	<input type="button" value="v"/>
Aircon Pump	No Fault Code	<input type="button" value="v"/>
Aircon Condensor	No Visible Leaks	<input type="button" value="v"/>
Interior Fan	No Fault Code	<input type="button" value="v"/>
Interior Radiator	No Visible Leaks	<input type="button" value="v"/>

Fueling System		
Intake Manifold	Within Specification	<input type="button" value="v"/>
Throttle	No Fault Code	<input type="button" value="v"/>
Turbo	No Fault Code	<input type="button" value="v"/>
Injectors	No Fault Code	<input type="button" value="v"/>
Fuel Pump	No Fault Code	<input type="button" value="v"/>
Fuel Lines	No Visible Leaks	<input type="button" value="v"/>

Ignition System		
Ignition Coils	No Fault Code	<input type="button" value="v"/>
Glow Plugs	Not Applicable	<input type="button" value="v"/>
Distributor	Not Applicable	<input type="button" value="v"/>
HT Leads	Not Applicable	<input type="button" value="v"/>

Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	Not Applicable	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	No Visible Leaks	<input type="checkbox"/>
CV Boots	No Visible Leaks	<input type="checkbox"/>
Shocks Front	No Visible Leaks	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Visible Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Visible Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	No Visible Leaks	<input type="checkbox"/>
Gear & Diff oil	No Visible Leaks	<input type="checkbox"/>
Auto Transmission	Within Specification	<input type="checkbox"/>
Gear Selector	Within Specification	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Code	<input type="checkbox"/>
Cyl Leakage Test	No Visible Leaks	<input type="checkbox"/>
Road Test	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Concluding Remarks

Bosch Technician

Dries Olwagen

General Comments

NEW Technician

Date of Inspection