

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-09-27 13:14:14
Technician Name: Dries
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2023
Make: HYUNDAI
Model: Venue(QXI)
VIN: MALFB81AVPM372933
Displacement: G 1.0 T-GDI KAPPA
Odometer: 47931 km
Vehicle Software Version: V10.40

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. IMT (Intelligent Manual Transmission)
3. DCT (Double Clutch Transmission)
4. ABS (Anti-lock Braking System)/ESP (Electronic Stability Program)
5. Airbag(Event #1)
6. Airbag(Event #2)
7. AC (Air Conditioning)
8. Cluster Module(3.5inch)
9. Cluster Module(4.2inch)
10. Integrated Body Control Unit-BCM
11. Integrated Body Control Unit-IMMO
12. Integrated Body Control Unit-SMK
13. Integrated Body Control Unit-TPMS
14. MDPS (Motor Driven Power Steering)
15. ICCU (Integrated Central Control Unit)
16. CODE (Transmitter Code Saving)