

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:2024-09-30 14:05:00

Technician Name:Christiaan

Order no:

Service fee:

Notes:

Vehicle Information

Year:2017

Make:TOYOTA

Model:Hilux

VIN:AHTGA3DC900873282

Displacement:D 2.5 TCI-A2

Odometer:117594.00 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMECT (Engine and ECT)
- 3.CCS (Cruise Control)
- 4.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)/TRC (Traction Control System)
- 5.SRS (Supplemental Inflatable Restraint System)
- 6.FWD (Four Wheel Drive)
- 7.CM (Combination Meter)
- 8.NS (Navigation System)
- 9.HAL (HL AutoLeveling)