

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-08 12:12:19
Technician Name: Riaan
Customer Name: citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Make: NISSAN
Displacement: D 2.2 TCI-R
Odometer: 92810 km
Vehicle Software Version: V10.32

Inspection Result

The following systems are OK:

1. ENGINE
2. ABS
3. METER/M&A
4. BCM
5. AIR BAG
6. EPS/DAST 3
7. IPDM E/R