

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16967

Make	NISSAN		
Model	NP200 1.6 A/C SAFETY PACK P/U S/C		
Vin	ADNUSN1D5U017342	25	
Engine Specifications	1.6	Petrol	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2019
Km	136282
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	•
Side Mirrors / Electric	Not Applicable	-	Wiper Blades	Renewed	•

## **BOSCH VEHICLE INSPECTION**

Engine					
Oil Service		136286 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Within Specification	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Renewed	•
Air Filter	Within Specification	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	•	Alternator Belt	Renewed	•
Spark Plugs	Within Specification	•	Power Steering Belt	Renewed	•
Brake Fluid	Within Specification	•	Aircon Belt	Renewed	•
Antifreeze	Within Specification	•	Multi V belt	Renewed	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Renewed	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	-
Rear Linings	80%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	-
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	-

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	-
Turbo	Not Applicable	-
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	No Fault Code	-



# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16967

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Renewed	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Within Specification	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	-

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

-Select-

### General Comments

Date of Inspection

11-Nov-2024



HENDRIE

## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

