

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-09-27 11:15:59
Technician Name: Riaan
Customer Name: citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2022
Make: KIA
Model: RIO(YB)
VIN: KNADB518LN6744266
Displacement: G 1.2 MPI KAPPA PE
Odometer: 49013 km
Vehicle Software Version: V10.46

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS/ESP
3. Airbag(Event #1)
4. Airbag(Event #2)
5. AC (Air Conditioning)
6. IC (Instrument Cluster)
7. Integrated Body Control Unit-BCM
8. Integrated Body Control Unit-IMMO
9. i-TPMS(Tire Pressure Monitoring System)
10. MDPS (Motor Driven Power Steering)
11. CODE (Transmitter Code Saving)