

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:01/31/2025 08:36:53
Technician Name:RICARDO

Vehicle Information

Year:2020
Make:HYUNDAI
Model:i20(IB)
VIN:MALBM51BLLM753987
Displacement:G 1.2 MPI
Odometer:74196 km
Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:
1.ECM (Engine Control Module)
2.ABS (Anti-lock Braking System)
3.Airbag(Event #1)
4.Airbag(Event #2)
5.IC (Cluster Module)
6.BCM (Body Control Module)
7.MDPS (Motor Driven Power Steering)
8.IMMO (Immobilizer)
9.CODE (Transmitter Code Saving)