Make	ТОУОТА		
Model	HILUX 2.8 GD-6 RB RAIDER P/U E/CAB		
Vin	AHTGA3DC20087592	25	
Engine Specifications	2.8	Diesel ▼	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2020
Km	99554
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Working Condition	-	Aircon Controls	Working Condition	•
Cluster	Good Condition	•	Electric Windows	Working Condition	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DONE Km		Dip Stick	Good Condition	•
Oil Filter	Renewed		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	No Visible Leaks		Fan Belt	No Cracks	V
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Not Applicable		Power Steering Belt	No Cracks	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	—
Antifreeze	No Visible Leaks ▼		Multi V belt	No Cracks	~
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	—
Sump/Gasket	No Visible Leaks ▼		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	No Visible Leaks	
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	V
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	Within Specification	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	~

Fueling System		
Intake Manifold	Within Specification	V
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	V

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Not Applicable	•
CV Boots	Not Applicable	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	—

Transmission & Clutch		
Clutch Kit	Good Condition	-
Clutch Master	No Visible Leaks	-
Clutch Slave	No Visible Leaks	—
Clutch Cable	Not Applicable	—
Gearbox	Within Specification	—
Gear & Diff oil	No Visible Leaks	—
Auto Transmission	Not Applicable	-
Gear Selector	Good Condition	—
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Bosch Technician		General Comments
Raymond Mncube	•	



NEW Technician

Concluding Remarks



Date of Inspection

13-Jan-2025