

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 2024-09-11 08:39:24
Technician Name: Raymond
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2016
Make: USAFORD
Model: Fiesta MY2013
VIN: WF0DXXGAKDGT76051
Displacement: G 1.2 MPI KAPPA PE
Odometer: 89487 km
Vehicle Software Version: V10.86

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCMII (Body Control Module)
5. DDM (Driver Front Door Module)
6. FCDIM (Front Control/Display Interface Module)
7. GPSM (Global Positioning System Module)
8. IPC (Instrument Panel Control Module)
9. PCM (Powertrain Control Module)
10. PDM (Passenger Front Door Module)
11. PSCM (Power Steering Control Module)
12. RCM (Restraint Control Module)
13. TCM (Transmission Control Module)