

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:01/29/2025 17:05:21
Technician Name:dries

Vehicle Information

Make:SUZUKI
VIN:MBHCZC63S00766920
Displacement:G 1.2 MPI KAPPA
Odometer:60187 km
Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-Lock Braking System)
- 3.EPS (Electronic Power Steering)
- 4.SRS (Supplemental Inflatable Restraint System/Airbag)
- 5.BCM (Body Control Module)
- 6.IPC (Combination Meter / Meter/ M&A)
- 7.CGW (Central Gateway Control Module)