

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 15091

Make	FORD		
Model	ECOSPORT 1.5TiVCT AMBIENTE A/T		
Vin	WDD1173522N15005	3	
Engine Specifications	1.5	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2022
Km	52929
Transmission	Automatic
Colour	BLACK
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION

Oil Service		52929 Km	Dip Stick	Good Condition	•
Oil Filter	Renewed	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	-	Fan Belt	Good Condition	•
Air Filter	Good Condition	-	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition	•	Alternator Belt	Good Condition	-
Spark Plugs	Good Condition	-	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	•	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	•	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	•	Engine Mountings	Good Condition	•
Sump/Gasket	Good Condition	-	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	100%	-
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	60%	-
Rear Brake Discs	Not Applicable	-
Rear Brake Sensor	Not Applicable	•
Rear Drums	Good Condition	-
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	-

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Good Condition	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	-
Wheel Alignment	Good Condition	•
CV Joints	Good Condition	-
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	-
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	-
Bearing Hubs	Good Condition	-
Control Arms	Good Condition	-
Sideshafts/Seal	Good Condition	•
Propshaft	Good Condition	•
Wheel Nuts/Studs	Good Condition	-
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	-

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Good Condition	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	-
Cyl Leakage Test	Good Condition	-
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

