

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-09-10 15:53:04

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2022

Make:KIA

Model:RIO(YB)

VIN:KNADB518LN6777930

Displacement:G 1.2 MPI KAPPA PE

Odometer:32561 km

Vehicle Software Version:V10.46

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS/ESP
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.AC (Air Conditioning)
- 6.IC (Instrument Cluster)
- 7.Integrated Body Control Unit-BCM
- 8.Integrated Body Control Unit-IMMO
- 9.i-TPMS(Tire Pressure Monitoring System)
- 10.MDPS (Motor Driven Power Steering)
- 11.CODE (Transmitter Code Saving)