

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: johan@boschgezina.co.za
Sn: 988579800333
Time: 2024-04-18 14:04:44
Technician Name: Raymond
Order no:
Service fee:
Notes:

Vehicle Information

Make: INDIANMAHINDRA
VIN: MA1YV2VMVN6078352
Displacement: G 2.0 MPI
Odometer: 046694 km
Vehicle Software Version: V10.34

Inspection Result

The following systems are OK:

- 1.EMS(ENGINE MANAGEMENT SYSTEM)
- 2.IC(INSTRUMENT CLUSTER)
- 3.MBFM(BODY FUNCTION MODULE)
- 4.SRS(SUPPLEMENTARY RESTRAINT SYSTEM)
- 5.HVAC(Heating Ventilation Air-conditioning and Cooling)
- 6.ABS(ANTI-LOCK BRAKING SYSTEM)
- 7.IS(INFOTAINMENT SYSTEM)
- 8.TCU(TRANSMISSION CONTROL UNIT)
- 9.IMMOBILISER