

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 16255

Make	VOLKSWAGEN		
Model	TIGUAN ALLSPACE 1.4 TSI C/LINE DSG (110)		
Vin	WVGZZZ5NZKM178911		
Engine Specifications	1.4	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2020
Km	52656
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Good Condition	•
Cluster	Within Specification	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	•	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION

8			
Oil Service	SERVICE DUE Km	Dip Stick	Within Specification
Oil Filter	Not Applicable	Oil Filler Cap	No Visible Leaks
Fuel/Diesel Filter	Within Specification	Fan Belt	Good Condition
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	Good Condition
Spark Plugs	Within Specification	Power Steering Belt	Not Applicable
Brake Fluid	Good Condition	Aircon Belt	Good Condition
Antifreeze	Good Condition	Multi V belt	Good Condition
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification

BOSCH INSPECTION REPORT

Braking	System
•	

Front Brake Pads	-Select-	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Renewed	-
Rear Brake Sensor	Within Specification	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	-
Brake Master	Good Condition	•
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	-
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	-
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Good Condition	-
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	-
Turbo	Within Specification	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Not Applicable	•
Mag Wheels/Hub Caps	Not Applicable	-

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Not Applicable	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Good Condition	-
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

RIAAN MEINTJIES

-Select-

General Comments

Date of Inspection

03-Oct-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

