

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 17104

Make	VOLKSWAGEN		
Model	MOVE UP! 1.0 5DR		
Vin	WVWZZZAAZKD17	9456	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2019
Km	100768
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION

Oil Service		100768 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Renewed	•	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	•	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	•	Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification	•	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	•	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	-
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•



Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Renewed	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	•



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	-
Wheel Alignment	Renewed	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	•
Gearbox	Good Condition	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

General Comments

Date of Inspection

15-Nov-2024



HENDRIE

BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

