

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: pieter@boschgezina.co.za

Sn: 988579800333

Time: 2024-08-03 11:04:17

Technician Name: Mike Jones

Order no:

Service fee:

Notes:

Vehicle Information

Make: RENAULT

Model: KWID

VIN: MEEBBA00400798298

Displacement: G 1.6 MPI

Odometer: 45120 km

Vehicle Software Version: V10.38

Inspection Result

The following systems are OK:

1. ECM (Engine Control Module)
2. ABS (Anti-lock Braking System)
3. IC (Instrument Cluster)
4. UCH
5. SRS (Supplemental Inflatable Restraint System)
6. Variable P.A.S