

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/18/2024 11:19:56

Technician Name:Ricardo

Vehicle Information

Make:BENZ

Model:156.952 - Mercedes-AMG GLA 45 4MATIC

VIN:WDC1569522J080171

Displacement:G 2.0 MPI

Odometer:91087 km

Vehicle Software Version:V10.98

Inspection Result

The following systems are OK:

- 1.AWD - All - Wheel Drive
- 2.FSCU - Fuel Pump
- 3.ME - MOTOR ELECTRONICS FOR COMBUSTION ENGINE(ECM)
- 4.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 5.EFB - Electric Parking Brake(EPB)
- 6.ES - Electronic Power Steering
- 7.ESP - Electronic Stability Program
- 8.DTR - DITRONIC
- 9.IRS_HRA - Outer Right Rear Intelligent Radar Sensor System
- 10.IRS_HLA - Outer Left Rear Intelligent Radar Sensor System
- 11.MFK - Multifunction Camera
- 12.PTS - PARKTRONIC
- 13.RFK - Backup Camera
- 14.TPC - Tire Pressure Monitoring System(TPMS)
- 15.EIS/EZS - Electronic Ignition Lock
- 16.ATA - Interior Motion Sensor
- 17.SCM - Steering Column Module
- 18.PSD - Panoramic Sliding Sunroof
- 19.HKS - Power Tail Gate(PTG)
- 20.RevGUS_VL - Left Front Reversible Emergency Tensioning Retractor
- 21.RevGUS_VR - Right Front Reversible Emergency Tensioning Retractor
- 22.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 23.AB - Supplemental Restraint System
- 24.SG-SW Control Unit 'Headlamp'(N71/1)
- 25.DSI - DIRECT SELECT interface(N150)

- 26.CPF - Camera Cover
- 27.COU[ZBE] - Audio/COMAND Operating Unit
- 28.ZAN - Audio/COMAND Display
- 29.Audio - Audio Or COMAND
- 30.IC - Instrument Cluster
- 31.MIF - Media Interface
- 32.ESA Front Passenger - Electrical Seat Adjustment Front Passenger
- 33.ESA Driver - Electrical Seat Adjustment Driver
- 34.DCU_FL - Left Front Door
- 35.DCU_FR - Right Front Door
- 36.AC - Air Conditioning
- 37.LIN: H3/1 - Alarm siren (AS)
- 38.LIN: A67 - Dimming inside rearview mirror(AISP)
- 39.LIN: N70 - Overhead control panel(OCP)
- 40.LIN: B95 - Battery sensor(BSN)
- 41.LIN: B38/2 - Rain/light sensor(RGLS)
- 42.LIN: N110 - Weight sensing system (WSS)
- 43.LIN: E1n7 - Actuation module, LED exterior lighting, left front(AMLAB-L)
- 44.LIN: E2n7 - Actuation module, LED exterior lighting, right front(AMLAB-R)
- 45.LIN: S22 - Switch group "Left front seat adjustment"(SSE-LF)
- 46.LIN: S23 - Switch group "Right front seat adjustment"(SSE-RF)