



Make	MAHINDRA	
Model	TUV300 1.5TD MHAWK (7 SEAT)	
Vin	MM6DJ2HAAJW341600	
Engine Specifications	1.5	Petrol <input type="checkbox"/>
Vehicle Type	SUV	
Service Plan	N/A	

Year	2020	
Km	126552	
Transmission	Manual	<input type="checkbox"/>
Colour	SILVER	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Good Condition	<input type="checkbox"/>	Aircon Controls	Good Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Good Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Renewed	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	124000 Km	Dip Stick	No Visible Leaks	<input type="checkbox"/>
Oil Filter	Within Specification	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	Within Specification	Fan Belt	Good Condition	<input type="checkbox"/>
Air Filter	Within Specification	Fan belt Tensioner	Good Condition	<input type="checkbox"/>
Cabin Filter	Within Specification	Alternator Belt	Good Condition	<input type="checkbox"/>
Spark Plugs	Not Applicable	Power Steering Belt	Good Condition	<input type="checkbox"/>
Brake Fluid	Within Specification	Aircon Belt	Good Condition	<input type="checkbox"/>
Antifreeze	Within Specification	Multi V belt	Good Condition	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	100%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	60%	<input type="checkbox"/>
Rear Brake Discs	Not Applicable	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Within Specification	<input type="checkbox"/>
Rear Linings	60%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	Good Condition	<input type="checkbox"/>
Aircon Pump	Good Condition	<input type="checkbox"/>
Aircon Condensor	Good Condition	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	No Fault Code	<input type="checkbox"/>
Turbo	No Fault Code	<input type="checkbox"/>
Injectors	No Fault Code	<input type="checkbox"/>
Fuel Pump	No Fault Code	<input type="checkbox"/>
Fuel Lines	No Visible Leaks	<input type="checkbox"/>

Ignition System		
Ignition Coils	Not Applicable	<input type="checkbox"/>
Glow Plugs	No Fault Code	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	▼
Power Steering Pump	Good Condition	▼
Wheel Alignment	Good Condition	▼
CV Joints	Good Condition	▼
CV Boots	Good Condition	▼
Shocks Front	Good Condition	▼
Shock Mountings Front	Good Condition	▼
Shocks Rear	Good Condition	▼
Stabilizer Links	Good Condition	▼
Wheel Bearings	Good Condition	▼
Bearing Hubs	Good Condition	▼
Control Arms	Good Condition	▼
Sideshafts/Seal	Good Condition	▼
Propshaft	Good Condition	▼
Wheel Nuts/Studs	Good Condition	▼
Tyres & Spare	Good Condition	▼
Mag Wheels/Hub Caps	Good Condition	▼

Transmission & Clutch		
Clutch Kit	Good Condition	▼
Clutch Master	Good Condition	▼
Clutch Slave	Good Condition	▼
Clutch Cable	Not Applicable	▼
Gearbox	Good Condition	▼
Gear & Diff oil	Good Condition	▼
Auto Transmission	Not Applicable	▼
Gear Selector	Good Condition	▼
Gear Linkages	Good Condition	▼

Ignition System		
Diagnostics	No Fault Code	▼
Cyl Leakage Test	Good Condition	▼
Road Test	Good Condition	▼
Handling	Good Condition	▼

Concluding Remarks	

Bosch Technician	
-Select- ▼	

General Comments	

NEW Technician	
HENDRIE	

Date of Inspection	
04-Sep-2024	