

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-10-23 16:41:56
Technician Name:john
Order no:
Service fee:
Notes:

Vehicle Information

Year:2020
Make:HYUNDAI
Model:i20(IB)
VIN:MALBM51BLLM810534
Displacement:G 1.2 MPI
Odometer:69659 km
Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.AC (Air Conditioning)
- 6.IC (Cluster Module)
- 7.BCM (Body Control Module)
- 8.MDPS (Motor Driven Power Steering)
- 9.IMMO (Immobilizer)
- 10.CODE (Transmitter Code Saving)