

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-08-20 13:58:36

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Year:2022

Make:MAZDA

Model:MAZDA2 / DEMIO

VIN:MM6DJ2HA6NW821607

Displacement:G 1.2 MPI

Odometer:27877 km

Vehicle Software Version:V10.34

Inspection Result

The following systems are OK:

- 1.BCM#1 (Body Control Module)
- 2.IC (Instrument Cluster)
- 3.PCM (Powertrain Control Module)
- 4.RCM (Restraint Control Module)
- 5.ABS (Anti-Lock Brake System)
- 6.ALM#1 (Auto Leveling Module)
- 7.CMU (Connectivity Master Unit)
- 8.EPS (Electronic Power Steering)
- 9.ESU (Electric Supply Unit)
- 10.SSU#1 (Start Stop Unit)