

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-10-22 11:27:18

Technician Name:john

Order no:

Service fee:

Notes:

Vehicle Information

Make:IVECO

VIN:ZCFCB35A805183072

Odometer:096989 km

Vehicle Software Version:V10.22

Inspection Result

The following systems are OK:

1.Engine

2.Braking Systems

3.BODY COMPUTER

4.Dashboard

5.Airbag TRW - SDM

6.BOSCH Radio Receiver - RRM

7.Delphi Radio Receiver - DAB