

All System Diagnostic Report

*

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: pieter@boschgezina.co.za
Sn: 988579800333
Time: 11/12/2024 15:00:16
Technician Name: hennie

Vehicle Information

Year: 2015
Make: USAFORD
Model: Focus
VIN: WF05XXGCC5FC83852
Odometer: 170083 km
Vehicle Software Version: V10.86

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCMII (Body Control Module)
5. DDM (Driver Front Door Module)
6. FCDIM (Front Control/Display Interface Module)
7. FDMS (Front Distance Sensing Module)
8. GPSM (Global Positioning System Module)
9. HVAC (Heating Ventilation Air Conditioning)
10. IPC (Instrument Panel Control Module)
11. IPM-A (Image Processing Module A)
12. PAM (Parking Aid Module)
13. PCM (Powertrain Control Module)
14. PDM (Passenger Front Door Module)
15. PSCM (Power Steering Control Module)
16. RCM (Restraint Control Module)
17. SASM (Steering Angle Sensor Module)