








BOSCH INSPECTION REPORT

JOB CARD NUMBER 18411




















Make	KIA		
Model	PICANTO 1.2 STREET		
Vin	KNAB2512LJT084243		
Engine Specifications	1.2	Petrol	<input type="checkbox"/>
Vehicle Type	H/B		
Service Plan	N/A		













Year	2018		
Km	95189		
Transmission	Manual		
Colour	WHITE		
Branch	Bosch Car Service		
Warranty Plan	N/A		

Interior					
Radio / Entertainment	No Fault Code			Aircon Controls	No Fault Code 
Cluster	No Fault Code			Electric Windows	No Fault Code 







Exterior					
Windscreen	Within Specification			Mag Wheels	Within Specification 
Side Mirrors / Electric	Within Specification			Wiper Blades	Within Specification 



BOSCH VEHICLE INSPECTION

Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	
Fuel/Diesel Filter	Not Applicable		Fan Belt	Not Applicable	
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	
Cabin Filter	Within Specification		Alternator Belt	No Cracks	
Spark Plugs	No Fault Code		Power Steering Belt	Not Applicable	
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	

Braking System		
Front Brake Pads	100%	
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	
Rear Drums	Within Specification	
Rear Linings	80%	
Brake Master	No Visible Leaks	
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	
Brake Hose	No Visible Leaks	

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	
Waterpump	No Visible Leaks	
Thermostat	No Visible Leaks	
Aircon Gas	No Visible Leaks	
Aircon Pump	No Fault Code	
Aircon Condensor	No Visible Leaks	
Interior Fan	No Fault Code	
Interior Radiator	No Visible Leaks	

Fueling System		
Intake Manifold	Within Specification	
Throttle	No Fault Code	
Turbo	Not Applicable	
Injectors	No Fault Code	
Fuel Pump	No Fault Code	
Fuel Lines	No Visible Leaks	

Ignition System		
Ignition Coils	No Fault Code	
Glow Plugs	Not Applicable	
Distributor	Not Applicable	
HT Leads	Not Applicable	

Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	Not Applicable	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	No Visible Leaks	<input type="checkbox"/>
Shocks Front	No Visible Leaks	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Visible Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Visible Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Within Specification	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Within Specification	<input type="checkbox"/>
Gearbox	No Visible Leaks	<input type="checkbox"/>
Gear & Diff oil	No Visible Leaks	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Within Specification	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Code	<input type="checkbox"/>
Cyl Leakage Test	No Visible Leaks	<input type="checkbox"/>
Road Test	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Concluding Remarks

Bosch Technician
Dries Olwagan <input type="checkbox"/>

General Comments

NEW Technician

Date of Inspection