

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:12/06/2024 13:14:34
Technician Name:Riaan
Customer Name:citton

Vehicle Information

Year:2019
Make:HYUNDAI
Model:i20(IB)
VIN:MALBM51BLKM684497
Displacement:G 1.2 MPI
Odometer:111265 km
Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.Body Control Module
- 6.Cluster Module
- 7.EPS (Electronic Power Steering)
- 8.IMM (Immobilizer)
- 9.CODE (Transmitter Code Saving)