

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: jaco@boschgezina.co.za

Sn: 988579800333

Time: 2024-10-01 13:34:33

Technician Name: Ricardo

Order no:

Service fee:

Notes:

Vehicle Information

Year: 2015

Make: USAFORD

Model: Fiesta MY2013

VIN: WF0DXXGAKDFP85556

Displacement: G 1.2 MPI KAPPA

Odometer: 117737 km

Vehicle Software Version: V10.86

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCMII (Body Control Module)
5. DDM (Driver Front Door Module)
6. FCDIM (Front Control/Display Interface Module)
7. GPSM (Global Positioning System Module)
8. IPC (Instrument Panel Control Module)
9. PCM (Powertrain Control Module)
10. PDM (Passenger Front Door Module)
11. PSCM (Power Steering Control Module)
12. RCM (Restraint Control Module)