Make	NISSAN	
Model	NP200 1.5 DCi A/C SAFETY PACK P/U S/C	
Vin	ADNUSN365U018579	11
Engine Specifications	1.5	Diesel
Vehicle Type	S/C	
Service Plan	N/A	

Year	2021
Km	129269
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	No Fault Code	•
Cluster	Within Specification	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	<b>—</b>	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Good Condition	_

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	No Visible Leaks	<b>V</b>	Fan Belt	Not Applicable	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	Good Condition	•
Spark Plugs	Not Applicable	•	Power Steering Belt	Good Condition	•
Brake Fluid	Within Specification	<b>~</b>	Aircon Belt	Good Condition	•
Antifreeze	Within Specification	_	Multi V belt	Good Condition	•
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	<b>~</b>	PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	•
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	<b>V</b>
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	~
Thermostat	No Visible Leaks	_
Aircon Gas	Good Condition	_
Aircon Pump	No Fault Code	<b>\rightarrow</b>
Aircon Condensor	No Visible Leaks	<b>V</b>
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	-
Throttle	No Fault Code	•
Turbo	Good Condition	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	lacksquare

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	No Fault Code	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Within Specification	lacksquare
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	
Clutch Master	No Visible Leaks	•
Clutch Slave	No Visible Leaks	•
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	<b>T</b>
Gear Linkages	Within Specification	<b>T</b>

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



