

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-21 14:14:02
Technician Name: Dries
Order no:
Service fee:
Notes:

Vehicle Information

Make: NISSAN
Model: np200
VIN: adnusn365u0185791
Odometer: 129292 km
Vehicle Software Version: V10.48

Inspection Result

The following systems are OK:

1. Engine Control Module (ECM)
2. Anti-lock Brake System (ABS)
3. Body Control System (BCM)
4. Supplemental Restraint System (SRS)
5. Electric Power Steering (EPS)