Make	FORD	
Model	FIESTA 1.0 ECOBOOST TREND 5DR A/T	
Vin	WF0JXXGAHJJB86154	
Engine Specifications	1.0 Petrol	
Vehicle Type	H/B	
Service Plan	N/A	

Year	2019
Km	52672
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	-	Aircon Controls	No Fault Code	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	V
Side Mirrors / Electric	No Fault Code	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Good Condition		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable		Fan Belt	Not Applicable	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks		Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	No Visible Leaks	•

Braking System		
Front Brake Pads	80%	—
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	—
Rear Brake Pads	-Select-	—
Rear Brake Discs	Not Applicable	—
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	—
Rear Linings	60%	—
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	—
Brake Calipers	No Visible Leaks	—
Brake Hose	No Visible Leaks	—

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	~
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	V
Aircon Condensor	No Visible Leaks	lacksquare
Interior Fan	No Fault Code	lacksquare
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	-
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	—



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	—
Clutch Cable	Not Applicable	—
Gearbox	No Visible Leaks	—
Gear & Diff oil	No Visible Leaks	-
Auto Transmission	No Visible Leaks	-
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	—

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	~
Road Test	Within Specification	-
Handling	Within Specification	T

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



PRETORIA

