

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 11/01/2024 14:44:28

Technician Name: Riaan

## Vehicle Information

Year: 2018

Make: USAFORD

Model: Fiesta

VIN: WF0JXXGAHJJ86246

Displacement: D 1.4 TCI-U2

Odometer: 108933 km

Vehicle Software Version: V10.86

## Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Brake System)
2. ACM (Audio Front Control Module)
3. BCM (Body Control Module)
4. DDM (Driver Door Module)
5. GWM (Gateway Module A)
6. HVAC (Heating, Ventilation And Air Conditioning)
7. IPC (Instrument Panel Cluster)
8. PAM (Parking Assist Control Module)
9. PCM (Powertrain Control Module)
10. PDM (Passenger Door Module)
11. PSCM (Power Steering Control Module)
12. RCM (Restraints Control Module)
13. SCCM (Steering Column Control Module)