



Make	HYUNDAI	
Model	i10 1.1 GLS/MOTION	
Vin	MALAN51BLHM687180	
Engine Specifications	1.1	Petrol <input type="checkbox"/>
Vehicle Type	H/B	
Service Plan	N/A	

Year	2017	
Km	50038	
Transmission	Manual	<input type="checkbox"/>
Colour	WHITE	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Good Condition	<input type="checkbox"/>	Aircon Controls	Good Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Good Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Good Condition	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	5003871139 Km		Dip Stick	Good Condition	<input type="checkbox"/>
Oil Filter	Renewed	<input type="checkbox"/>	Oil Filler Cap	Good Condition	<input type="checkbox"/>
Fuel/Diesel Filter	Good Condition	<input type="checkbox"/>	Fan Belt	Good Condition	<input type="checkbox"/>
Air Filter	Good Condition	<input type="checkbox"/>	Fan belt Tensioner	Good Condition	<input type="checkbox"/>
Cabin Filter	Good Condition	<input type="checkbox"/>	Alternator Belt	Good Condition	<input type="checkbox"/>
Spark Plugs	Good Condition	<input type="checkbox"/>	Power Steering Belt	Good Condition	<input type="checkbox"/>
Brake Fluid	Good Condition	<input type="checkbox"/>	Aircon Belt	Good Condition	<input type="checkbox"/>
Antifreeze	Good Condition	<input type="checkbox"/>	Multi V belt	Good Condition	<input type="checkbox"/>
Rear Main Seal	Good Condition	<input type="checkbox"/>	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	Good Condition	<input type="checkbox"/>	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="button" value="v"/>
Front Brake Discs	Good Condition	<input type="button" value="v"/>
Front Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Brake Pads	-Select-	<input type="button" value="v"/>
Rear Brake Discs	Not Applicable	<input type="button" value="v"/>
Rear Brake Sensor	Not Applicable	<input type="button" value="v"/>
Rear Drums	Good Condition	<input type="button" value="v"/>
Rear Linings	60%	<input type="button" value="v"/>
Brake Master	Good Condition	<input type="button" value="v"/>
Hand Brake	Good Condition	<input type="button" value="v"/>
Brake Calipers	Good Condition	<input type="button" value="v"/>
Brake Hose	Good Condition	<input type="button" value="v"/>

Cooling System		
Radiator	Good Condition	<input type="button" value="v"/>
Radiator Hoses	Good Condition	<input type="button" value="v"/>
Waterpump	Good Condition	<input type="button" value="v"/>
Thermostat	Good Condition	<input type="button" value="v"/>
Aircon Gas	Good Condition	<input type="button" value="v"/>
Aircon Pump	Good Condition	<input type="button" value="v"/>
Aircon Condensor	Good Condition	<input type="button" value="v"/>
Interior Fan	Good Condition	<input type="button" value="v"/>
Interior Radiator	Good Condition	<input type="button" value="v"/>

Fueling System		
Intake Manifold	Good Condition	<input type="button" value="v"/>
Throttle	Good Condition	<input type="button" value="v"/>
Turbo	Not Applicable	<input type="button" value="v"/>
Injectors	Good Condition	<input type="button" value="v"/>
Fuel Pump	Good Condition	<input type="button" value="v"/>
Fuel Lines	Good Condition	<input type="button" value="v"/>

Ignition System		
Ignition Coils	Good Condition	<input type="button" value="v"/>
Glow Plugs	Not Applicable	<input type="button" value="v"/>
Distrubutor	Not Applicable	<input type="button" value="v"/>
HT Leads	Good Condition	<input type="button" value="v"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="checkbox"/>
Power Steering Pump	Good Condition	<input type="checkbox"/>
Wheel Alignment	Good Condition	<input type="checkbox"/>
CV Joints	Good Condition	<input type="checkbox"/>
CV Boots	Good Condition	<input type="checkbox"/>
Shocks Front	Good Condition	<input type="checkbox"/>
Shock Mountings Front	Good Condition	<input type="checkbox"/>
Shocks Rear	Good Condition	<input type="checkbox"/>
Stabilizer Links	Good Condition	<input type="checkbox"/>
Wheel Bearings	Good Condition	<input type="checkbox"/>
Bearing Hubs	Good Condition	<input type="checkbox"/>
Control Arms	Good Condition	<input type="checkbox"/>
Sideshafts/Seal	Good Condition	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Good Condition	<input type="checkbox"/>
Tyres & Spare	Good Condition	<input type="checkbox"/>
Mag Wheels/Hub Caps	Good Condition	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Good Condition	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Good Condition	<input type="checkbox"/>
Gearbox	Good Condition	<input type="checkbox"/>
Gear & Diff oil	Good Condition	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Good Condition	<input type="checkbox"/>
Gear Linkages	Good Condition	<input type="checkbox"/>

Ignition System		
Diagnostics	Good Condition	<input type="checkbox"/>
Cyl Leakage Test	Good Condition	<input type="checkbox"/>
Road Test	Good Condition	<input type="checkbox"/>
Handling	Good Condition	<input type="checkbox"/>

Concluding Remarks

Bosch Technician

Basal Johnson

General Comments

NEW Technician

Date of Inspection

17-Jul-2024