

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: jaco@boschgezina.co.za

Sn: 988579800333

Time: 11/08/2024 10:03:41

Technician Name: Christiaan

## Vehicle Information

Year: 2016

Make: HYUNDAI

Model: H-1/iMAX/iLOAD/Grand

VIN: KMFWBX7KMGU788082

Displacement: D 2.5 TCI-A2(Euro-6)

Odometer: 194257 km

Vehicle Software Version: V10.40

## Inspection Result

The following systems are OK:

1. TCM (Transmission Control Module)
2. ABS (Anti-lock Braking System)
3. Airbag (Event #1)
4. Airbag (Event #2)
5. BCM (Body Control Module)
6. CODE (Transmitter Code Saving)