

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co

Sn:988579800333

Time:2024-07-12 08:22:38

Technician Name:Basal

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2017

Make:HYUNDAI

Model:Elantra(AD)

VIN:KMHD841CLHU488264

Displacement:G 1.6 MPI

Odometer:125894 km

Vehicle Software Version:V10.30

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #2)
- 4.Airbag(Event #1)
- 5.AC (Air Conditioning)
- 6.Body Control Module
- 7.Cluster Module
- 8.Smart Junction Block
- 9.TPMS (Tire Pressure Monitoring System)
- 10.EPS (Electronic Power Steering)
- 11.IMM (Immobilizer)
- 12.CODE (Transmitter Code Saving)