

Mazda CX5 Dynamic A/T

Client Copy

Bosch Service Inspection Certificate

Inspection No:

BOSCH Service

BATTERY DETAILS

Age: 7/19/20 Registration No: 628

Registration No: CK24490

Job Card No: JC9260

Table with 15 columns: SERVICE, OK, Not Ok, Rectified, BREAKING SYSTEM, OK, Not Ok, Rectified, STEERING SYSTEM, OK, Not Ok, Rectified. Rows include items like Service, Spark Plugs, Oil, Brake Fluid, etc.

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

ROAD TEST

Performance, Noise, Handling, Transmission, Clutch. all good

Brakes, Vibrations, Wheel Alignment, Wheel Balancing. all good

BCS DEALERSHIP DECLARATION

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and of sound mechanical condition.

Technician Name: Michael Jones

Date: 08-01-2023 Signature: [Signature]

Service Advisor/Managers Name: print name

Signature:

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.