

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/07/2024 14:34:39

Technician Name:Elias

## Vehicle Information

Year:2014

Make:KIA

Model:RIO(UB)

VIN:KNADN512LE6892524

Displacement:G 1.4 DOHC

Odometer:106968 km

Vehicle Software Version:V10.50

## Inspection Result

The following systems are OK:

- 1.Engine(Unleaded All)
- 2.Engine(Leaded All)
- 3.ABS (Anti-Lock Brake System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.Body Control Module(EURO)
- 7.Body Control Module(GEN)
- 8.MDPS (Motor Driven Power Steering)
- 9.IMMO (Immobilizer)
- 10.CODE (Transmitter Code Saving)