

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/11/2024 14:50:13

Technician Name:Christiaan

Vehicle Information

Make:NISSAN

VIN:ADNUSN1L5U0089604

Displacement:G 1.4 DOHC

Odometer:147689 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.Body Control System(BCM)
- 2.Supplemental Restraint System(SRS)