

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16188

Make	KIA
Model	K 2500 P/U S/C
Vin	MALBM51BLLM731082
Engine Specifications	Diesel
Vehicle Type	S/C

Year	2022
Km	53495
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Not Applicable	•	Aircon Controls	Not Applicable	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Not Applicable	•	Mag Wheels	Good Condition	-
Side Mirrors / Electric	Good Condition	•	Wiper Blades	Not Applicable	-

# **BOSCH VEHICLE INSPECTION**

Engine				
Oil Service		53503 Km	Dip Stick	No Visible Leaks
Oil Filter	Good Condition	•	Oil Filler Cap	No Visible Leaks
Fuel/Diesel Filter	Good Condition	-	Fan Belt	Good Condition
Air Filter	Good Condition	-	Fan belt Tensioner	Good Condition
Cabin Filter	Not Applicable	•	Alternator Belt	Good Condition
Spark Plugs	Not Applicable	-	Power Steering Belt	Good Condition
Brake Fluid	No Visible Leaks	•	Aircon Belt	No Cracks
Antifreeze	No Visible Leaks	-	Multi V belt	Good Condition
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Good Condition
Sump/Gasket	No Visible Leaks	-	PCV Valve	Good Condition



Braking System		
Front Brake Pads	-Select-	-
Front Brake Discs	Not Applicable	•
Front Brake Sensor	Good Condition	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Good Condition	-
Rear Drums	Good Condition	-
Rear Linings	-Select-	•
Brake Master	Good Condition	-
Hand Brake	Good Condition	-
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	Not Applicable	•
Aircon Pump	Not Applicable	-
Aircon Condensor	Not Applicable	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	No Visible Leaks	-
Throttle	Good Condition	-
Turbo	Not Applicable	-
Injectors	No Visible Leaks	-
Fuel Pump	No Visible Leaks	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Good Condition	•
Distrubutor	No Visible Leaks	-
HT Leads	Good Condition	•



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	No Visible Leaks	•
Wheel Alignment	Not Applicable	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Good Condition	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Not Applicable	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Good Condition	•
Clutch Slave	Good Condition	•
Clutch Cable	Good Condition	•
Gearbox	Good Condition	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Good Condition	•
Cyl Leakage Test	No Visible Leaks	-
Road Test	Good Condition	•
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

-Select-

### General Comments

**NEW Technician** 

JOHN TSIPA

#### Date of Inspection



# BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

