

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 16912

Make	KIA	
Model	RIO 1.4 5DR	
Vin	KNADN512LE689252	4
Engine Specifications	1.4	Petrol 💌
Vehicle Type	H/B	
Service Plan	N/A	

Year	2013
Km	106962
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	•
Cluster	Within Specification	-	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

	·			
Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	-
Oil Filter R	Renewed	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter W	Vithin Specification	Fan Belt	Within Specification	•
Air Filter W	Vithin Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter W	Vithin Specification	Alternator Belt	Within Specification	•
Spark Plugs W	Vithin Specification	Power Steering Belt	Within Specification	•
Brake Fluid W	Vithin Specification	Aircon Belt	Within Specification	-
Antifreeze W	Vithin Specification	Multi V belt	Within Specification	•
Rear Main Seal N	Io Visible Leaks	Engine Mountings	Within Specification	-
Sump/Gasket N	lo Visible Leaks	PCV Valve	Within Specification	•



Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	-
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	-
Rear Brake Sensor	Within Specification	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	-
Brake Calipers	Within Specification	-
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	-
Glow Plugs	Not Applicable	-
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Renewed	•

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Fault Code	•
Road Test	Within Specification	•
Handling	Within Specification	•

#### **Concluding Remarks**

### Bosch Technician

Elias Makubela

**NEW Technician** 

### General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

