



## Vehicle Information

Brand: KIA	VIN: KNADC514MM6493168	Plate Number:
Model: Rio(YB)	Mileage:	Color:
Year: 2021	Capacity:	Status: Unset status
Engine: G 1.4 MPI KAPPA	Reference:	Date: 18.11.2024 12:58:08

## Automatic scanning results

System Name	Status/Count
01-ENG (Engine)	Pass   No Fault
02-A/T (Transaxle)	Pass   No Fault
03-EPS (Motor Driven Power Steering)	Pass   No Fault
04-ABS/ESP (Anti Lock Brake/Electronic Stability Program)	Pass   No Fault
05-AB (Airbag)	Pass   No Fault
06-A/C (Air Conditioner)	Pass   No Fault
07-CLU (Cluster Module)	Pass   No Fault
08-I-TPMS (I-Tire Pressure Monitoring System)	Pass   No Fault
09-RVM (Rear View Monitor)	Pass   No Fault
10-IBU-BCM (Integrated Body Control Unit-Body Control Module)	Pass   No Fault
11-CODE (Transmitter Code Saving)	Pass   No Fault
12-IBU-IMMO (Integrated Body Control Unit-Immobilizer)	Pass   No Fault



## Vehicle Diagnostic Report

---

Name:

Address: Pretoria Gauteng

Phone:

Email:

Website:

---

APP Version: 1.4.8