



Make	MERCEDES-BENZ
Model	A 250 AMG A/T
Vin	WDD1770462N094634
Engine Specifications	Petrol <input type="checkbox"/>
Vehicle Type	H/B
Service Plan	N/A

Year	2019
Km	42436
Transmission	Automatic <input type="checkbox"/>
Colour	YELLOW
Branch	Bosch Car Service
Warranty Plan	N/A

Interior

Radio / Entertainment	Good Condition <input type="checkbox"/>	Aircon Controls	Good Condition <input type="checkbox"/>
Cluster	Good Condition <input type="checkbox"/>	Electric Windows	Good Condition <input type="checkbox"/>

Exterior

Windscreen	Good Condition <input type="checkbox"/>	Mag Wheels	Good Condition <input type="checkbox"/>
Side Mirrors / Electric	Good Condition <input type="checkbox"/>	Wiper Blades	Good Condition <input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	42436 Km	Dip Stick	No Visible Leaks <input type="checkbox"/>
Oil Filter	Renewed <input type="checkbox"/>	Oil Filler Cap	No Visible Leaks <input type="checkbox"/>
Fuel/Diesel Filter	Within Specification <input type="checkbox"/>	Fan Belt	No Cracks <input type="checkbox"/>
Air Filter	Within Specification <input type="checkbox"/>	Fan belt Tensioner	Good Condition <input type="checkbox"/>
Cabin Filter	Within Specification <input type="checkbox"/>	Alternator Belt	No Cracks <input type="checkbox"/>
Spark Plugs	Within Specification <input type="checkbox"/>	Power Steering Belt	No Cracks <input type="checkbox"/>
Brake Fluid	Within Specification <input type="checkbox"/>	Aircon Belt	No Cracks <input type="checkbox"/>
Antifreeze	Within Specification <input type="checkbox"/>	Multi V belt	No Cracks <input type="checkbox"/>
Rear Main Seal	No Visible Leaks <input type="checkbox"/>	Engine Mountings	Good Condition <input type="checkbox"/>
Sump/Gasket	No Visible Leaks <input type="checkbox"/>	PCV Valve	Good Condition <input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	No Fault Code	<input type="checkbox"/>
Rear Brake Pads	100%	<input type="checkbox"/>
Rear Brake Discs	Renewed	<input type="checkbox"/>
Rear Brake Sensor	Renewed	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	-Select-	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	Good Condition	<input type="checkbox"/>
Aircon Pump	Good Condition	<input type="checkbox"/>
Aircon Condensor	Good Condition	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Good Condition	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Good Condition	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="button" value="v"/>
Power Steering Pump	Good Condition	<input type="button" value="v"/>
Wheel Alignment	Within Specification	<input type="button" value="v"/>
CV Joints	Good Condition	<input type="button" value="v"/>
CV Boots	No Visible Leaks	<input type="button" value="v"/>
Shocks Front	No Visible Leaks	<input type="button" value="v"/>
Shock Mountings Front	Good Condition	<input type="button" value="v"/>
Shocks Rear	No Visible Leaks	<input type="button" value="v"/>
Stabilizer Links	Good Condition	<input type="button" value="v"/>
Wheel Bearings	Good Condition	<input type="button" value="v"/>
Bearing Hubs	Good Condition	<input type="button" value="v"/>
Control Arms	Good Condition	<input type="button" value="v"/>
Sideshafts/Seal	No Visible Leaks	<input type="button" value="v"/>
Propshaft	Not Applicable	<input type="button" value="v"/>
Wheel Nuts/Studs	Good Condition	<input type="button" value="v"/>
Tyres & Spare	Good Condition	<input type="button" value="v"/>
Mag Wheels/Hub Caps	Good Condition	<input type="button" value="v"/>

Transmission & Clutch		
Clutch Kit	Not Applicable	<input type="button" value="v"/>
Clutch Master	Not Applicable	<input type="button" value="v"/>
Clutch Slave	Not Applicable	<input type="button" value="v"/>
Clutch Cable	Not Applicable	<input type="button" value="v"/>
Gearbox	Good Condition	<input type="button" value="v"/>
Gear & Diff oil	Good Condition	<input type="button" value="v"/>
Auto Transmission	Good Condition	<input type="button" value="v"/>
Gear Selector	Good Condition	<input type="button" value="v"/>
Gear Linkages	Good Condition	<input type="button" value="v"/>

Ignition System		
Diagnostics	No Fault Code	<input type="button" value="v"/>
Cyl Leakage Test	Good Condition	<input type="button" value="v"/>
Road Test	Good Condition	<input type="button" value="v"/>
Handling	Good Condition	<input type="button" value="v"/>

Concluding Remarks	

Bosch Technician	
-Select-	

General Comments	

NEW Technician	
HENDRIE	

Date of Inspection	
18-Nov-2024	