

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14190

Make	JEEP		
Model	WRANGLER 3.6 SPORT A/T 2DR		
Vin	1C4BJWHG5EL19529	99	
Engine Specifications	3.6	Petrol	
Vehicle Type	SUV		
Service Plan	N/A		

Year	2014
Km	133793
Transmission	Automatic
Colour	GREY
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	-	Wiper Blades	Within Specification	-

## **BOSCH VEHICLE INSPECTION**

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification
Oil Filter	Within Specification	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	Fan Belt	Not Applicable
Air Filter	Within Specification	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	Alternator Belt	Not Applicable
Spark Plugs	Within Specification	Power Steering Belt	Not Applicable
Brake Fluid	Within Specification	Aircon Belt	Not Applicable
Antifreeze	Within Specification	Multi V belt	Within Specification
Rear Main Seal	Within Specification	Engine Mountings	Within Specification
Sump/Gasket	Within Specification	PCV Valve	Within Specification

# BOSCH INSPECTION REPORT

Braking System		
Front Brake Pads	80%	-
Front Brake Discs	Within Specification	-
Front Brake Sensor	Not Applicable	-
Rear Brake Pads	80%	-
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	-
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	-

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	<b>~</b>
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	-
Aircon Pump	Within Specification	-
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	<b>~</b>

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	<b>•</b>
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	-
Gear & Diff oil	Within Specification	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	•
Cyl Leakage Test	Not Applicable	•
Road Test	Not Applicable	-
Handling	Not Applicable	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

MICHAEL JONES

-Select-

## General Comments

Date of Inspection

21-Jun-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

