



Make	HYUNDAI	
Model	i10 1.1 GLS/MOTION	
Vin	MALBM51BLLM731082	
Engine Specifications	1.1	Petrol <input type="checkbox"/>
Vehicle Type	H/B	
Service Plan	N/A	

Year	2015	
Km	163702	
Transmission	Manual	<input type="checkbox"/>
Colour	SILVER	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Good Condition	<input type="checkbox"/>	Aircon Controls	Good Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Good Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Good Condition	<input type="checkbox"/>	Wiper Blades	Renewed	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	163702 Km	Dip Stick	No Visible Leaks	<input type="checkbox"/>
Oil Filter	Renewed	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	Within Specification	Fan Belt	No Cracks	<input type="checkbox"/>
Air Filter	Within Specification	Fan belt Tensioner	Good Condition	<input type="checkbox"/>
Cabin Filter	Within Specification	Alternator Belt	No Cracks	<input type="checkbox"/>
Spark Plugs	Within Specification	Power Steering Belt	No Cracks	<input type="checkbox"/>
Brake Fluid	Within Specification	Aircon Belt	No Cracks	<input type="checkbox"/>
Antifreeze	Within Specification	Multi V belt	No Cracks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	PCV Valve	Good Condition	<input type="checkbox"/>

Braking System		
Front Brake Pads	80%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	-Select-	<input type="checkbox"/>
Rear Brake Discs	Not Applicable	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Within Specification	<input type="checkbox"/>
Rear Linings	60%	<input type="checkbox"/>
Brake Master	Good Condition	<input type="checkbox"/>
Hand Brake	Good Condition	<input type="checkbox"/>
Brake Calipers	Good Condition	<input type="checkbox"/>
Brake Hose	Good Condition	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	No Visible Leaks	<input type="checkbox"/>
Thermostat	No Visible Leaks	<input type="checkbox"/>
Aircon Gas	Good Condition	<input type="checkbox"/>
Aircon Pump	Good Condition	<input type="checkbox"/>
Aircon Condensor	Good Condition	<input type="checkbox"/>
Interior Fan	Good Condition	<input type="checkbox"/>
Interior Radiator	Good Condition	<input type="checkbox"/>

Fueling System		
Intake Manifold	Good Condition	<input type="checkbox"/>
Throttle	Good Condition	<input type="checkbox"/>
Turbo	Not Applicable	<input type="checkbox"/>
Injectors	Good Condition	<input type="checkbox"/>
Fuel Pump	Good Condition	<input type="checkbox"/>
Fuel Lines	Good Condition	<input type="checkbox"/>

Ignition System		
Ignition Coils	Good Condition	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distrubutor	Not Applicable	<input type="checkbox"/>
HT Leads	Good Condition	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Good Condition	<input type="checkbox"/>
Power Steering Pump	Good Condition	<input type="checkbox"/>
Wheel Alignment	Good Condition	<input type="checkbox"/>
CV Joints	Good Condition	<input type="checkbox"/>
CV Boots	No Visible Leaks	<input type="checkbox"/>
Shocks Front	Good Condition	<input type="checkbox"/>
Shock Mountings Front	Good Condition	<input type="checkbox"/>
Shocks Rear	Good Condition	<input type="checkbox"/>
Stabilizer Links	Renewed	<input type="checkbox"/>
Wheel Bearings	Good Condition	<input type="checkbox"/>
Bearing Hubs	Good Condition	<input type="checkbox"/>
Control Arms	Good Condition	<input type="checkbox"/>
Sideshafts/Seal	No Visible Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Good Condition	<input type="checkbox"/>
Tyres & Spare	Good Condition	<input type="checkbox"/>
Mag Wheels/Hub Caps	Good Condition	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Renewed	<input type="checkbox"/>
Clutch Master	Not Applicable	<input type="checkbox"/>
Clutch Slave	Not Applicable	<input type="checkbox"/>
Clutch Cable	Good Condition	<input type="checkbox"/>
Gearbox	Good Condition	<input type="checkbox"/>
Gear & Diff oil	Good Condition	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Good Condition	<input type="checkbox"/>
Gear Linkages	Good Condition	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Code	<input type="checkbox"/>
Cyl Leakage Test	Good Condition	<input type="checkbox"/>
Road Test	Good Condition	<input type="checkbox"/>
Handling	Good Condition	<input type="checkbox"/>

Concluding Remarks

Bosch Technician

-Select-

General Comments

NEW Technician

HENDRIE

Date of Inspection

02-Oct-2024