

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14065

Make	NISSAN		
Model	NP200 1.6 A/C SAFETY PACK P/U S/C		
Vin	ADNUSN1D5U019543	36	
Engine Specifications	1.6	Petrol	
Vehicle Type	S/C		
Service Plan	N/A		

Year	2021
Km	116459
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Not Applicable	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Not Applicable	-
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Good Condition	-

BOSCH VEHICLE INSPECTION

Oil Service	SERVICE DUE Km	Dip Stick	Within Specification	•
Oil Filter	Not Applicable	Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification	Fan Belt	Within Specification	•
Air Filter	Within Specification	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	Alternator Belt	Within Specification	•
Spark Plugs	Within Specification	Power Steering Belt	Within Specification	•
Brake Fluid	Good Condition	Aircon Belt	Within Specification	•
Antifreeze	Good Condition	Multi V belt	Within Specification	•
Rear Main Seal	No Visible Leaks	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

Description of	C
Braking	System
	-,

Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	Good Condition	-
Aircon Pump	Within Specification	-
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	-

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	-
Turbo	Not Applicable	-
Injectors	Not Applicable	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Within Specification	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	•
Stabilizer Links	Good Condition	•
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	•
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	•
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Not Applicable	•
Clutch Cable	Within Specification	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Not Applicable	•
Cyl Leakage Test	No Visible Leaks	•
Road Test	Good Condition	•
Handling	Good Condition	•

Concluding Remarks

Bosch Technician

NEW Technician

RIAAN MEINTJIES

-Select-

General Comments

Date of Inspection

19-Jun-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

