

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:2024-06-19 12:31:53
Technician Name:Riaan
Customer Name:citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Make:RENAULT
Model:LOGAN
VIN:ADNUSN1D540195436
Displacement:G 1.2 DOHC
Odometer:116465 km
Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.UCH
- 4.SRS (Supplemental Inflatable Restraint System)