Make	PEUGEOT	
Model	208 ALLURE 1.2 PURETECH 5DR	
Vin	VF3CCHMZ0KW096033	
Engine Specifications	1.2 Petrol	-
Vehicle Type	H/B	
Service Plan	N/A	

Year	2020
Km	110694
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>~</b>	Aircon Controls	No Fault Code	•
Cluster	Within Specification	•	Electric Windows	No Fault Code	-

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	<b>—</b>
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	<b>V</b>	Fan Belt	Not Applicable	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	<b>—</b>	Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	<b>—</b>	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	_	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	<b>—</b>	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	<b>V</b>	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	lacksquare
Rear Brake Discs	Not Applicable	
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	
Rear Linings	60%	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	-
Thermostat	No Visible Leaks	•
Aircon Gas	Good Condition	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	No Fault Code	•
Turbo	Not Applicable	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	No Visible Leaks	-
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	<b>—</b>
Clutch Master	No Visible Leaks	<b>—</b>
Clutch Slave	No Visible Leaks	<b>—</b>
Clutch Cable	Not Applicable	<b>~</b>
Gearbox	No Visible Leaks	<b>~</b>
Gear & Diff oil	No Visible Leaks	<b>—</b>
Auto Transmission	Not Applicable	<b>—</b>
Gear Selector	Within Specification	<b>—</b>
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



