Make	LAND ROVER	
Model	DISCOVERY SPORT 2.0D HSE (177KW)	
Vin	SALCA2AN1KH79774	14
Engine Specifications	2.0	Diesel
Vehicle Type	SUV	
Service Plan	N/A	

Year	2020
Km	84967
Transmission	Manual
Colour	BLUE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	-
Cluster	Within Specification	-	Electric Windows	Within Specification	-

Exterior					
Windscreen	Within Specification		Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		84967 Km	Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	lacksquare	Fan Belt	Within Specification	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	_	Alternator Belt	Not Applicable	•
Spark Plugs	Not Applicable		Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	_	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	_	Multi V belt	Not Applicable	<b>~</b>
Rear Main Seal	No Visible Leaks	_	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	80%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	_
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	_
Thermostat	Within Specification	_
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	_
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	<b>~</b>
Injectors	Within Specification	<b>~</b>
Fuel Pump	Within Specification	<b>~</b>
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	<b>—</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	-
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	lacksquare
CV Boots	Within Specification	
Shocks Front	Within Specification	lacksquare
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	lacksquare
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	<b>T</b>

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	lacksquare
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Within Specification	<b>V</b>
Auto Transmission	Within Specification	<b>V</b>
Gear Selector	Within Specification	<b>V</b>
Gear Linkages	Within Specification	<b>V</b>

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Not Applicable	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks			

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENNIE	28-Jan-2025



