

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-08-12 07:57:28

Technician Name:Dries

Order no:

Service fee:

Notes:

Vehicle Information

Year:2015

Make:KIA

Model:Soul(PS)

VIN:KNAJP814MF7797994

Displacement:G 2.0 NU MPI

Odometer:118984 km

Vehicle Software Version:V10.38

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ESP (Electronic Stability Program)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.AC (Air Conditioning)
- 7.IPM (Instrument Panel Module)
- 8.IC (Instrument Cluster)
- 9.SJB (Smart Junction Block)
- 10.Smart Key Unit(Button)
- 11.MDPS (Motor Driven Power Steering)
- 12.AHLS (Auto Headlamp Leveling System)
- 13.CODE (Transmitter Code Saving)