All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre Address:564 Steve Biko Road Telephone:0123355737 Sn:988579800333 Time:2024-10-17 16:24:46 Technician Name:Raymond Order no: Service fee: Notes:

Vehicle Information

Make:RENAULT Model:LOGAN II/SANDERO II VIN:VF15SRAA453498981 Odometer:120196 km Vehicle Software Version:V10.40

Inspection Result

The following systems are OK: 1.ECM (Engine Control Module) 2.ABS (Anti-lock Braking System) 3.IC (Instrument Cluster) 4.UCH 5.SRS (Supplemental Inflatable Restraint System) 6.Variable P.A.S 7.Radio