

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:johan@boschgezina.co.za

Sn:988579800333

Time:11/01/2024 16:25:22

Technician Name:Dries

## Vehicle Information

Make:RENAULT

Model:CAPTUR/QM3/KABIN

VIN:VF12R5A1H52599993

Displacement:D 1.4 TCI-U2

Odometer:113717 km

Vehicle Software Version:V10.40

## Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.UCH
- 3.ABS (Anti-lock Braking System)
- 4.IC (Instrument Cluster)
- 5.AC (Air Conditioning)
- 6.SRS (Supplemental Inflatable Restraint System)
- 7.Parking Prox Can
- 8.Radio
- 9.Variable P.A.S
- 10.UPC
- 11.Hands-Free Module